

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	0	(bevel and friction and gear and input and output and pressing and ring and registering and reaction and time).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/24 17:04
L3	0	(bevel and friction and gear and input and output and pressing and ring and registering and torque and force).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/24 17:05
L4	0	(bevel and friction and gear and input and output and pressing and ring and registering and reaction and time).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/24 17:06
L5	0	(bevel and friction and gear and input and output and pressing and operating and characteristic and curve).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/24 17:06

3/24/09 5:07:11 PM

C:\Documents and Settings\dfenstermacher\My Documents\EAST\Workspaces\\Default EAST Workspace (Flat Panel).wsp